# MASTERCAM 2018 README

May 2017





Be Dynamic.

#### **INTRODUCTION**

Please review this ReadMe for last-minute product information about Mastercam 2018. Report any problems to qc@mastercam.com.

## MASTERCAM 2018

| Category | Name                                                                                                 | Number  |
|----------|------------------------------------------------------------------------------------------------------|---------|
| General  | NetHASP licenses did not get released after failing and then succeeding to switch to another license | D-27512 |
| General  | Saving a file with clean operations and re-opening it showed misc dirty toolpaths                    | R-11553 |
| General  | Enabled Command Finder in Mastercam Demo/HLE                                                         | S-48018 |
| Tooling  | Face mill tool type with full radius was incorrectly projected                                       | S-48178 |

| Category  | Name                                                                                                                                                           | Number  |
|-----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|
| API       | Doing polygon or vector selection sometimes left<br>Mastercam in an undesirable state.                                                                         | D-27296 |
| General   | Mastercam crashed when attempting to open Inventor IDW files.                                                                                                  | D-26501 |
| General   | Zip2Go did not include .psb files.                                                                                                                             | R-11256 |
| General   | Updated Spatial API to version 2017 1.0.2 in support of handling of SAT, CATIA, Inventor, Alibre files. This provides support for the latest release of CATIA. | S-47765 |
| Graphics  | Arcs did not always display correctly after switching Viewsheets.                                                                                              | R-11509 |
| Toolpaths | The <b>Remove Spaces</b> NC file function in Code Expert changed NC code into one line.                                                                        | D-27457 |

| Category  | Name                                                                                                                        | Number  |
|-----------|-----------------------------------------------------------------------------------------------------------------------------|---------|
| General   | White geometry did not display in print preview                                                                             | R-11001 |
| General   | ASCII text data did not make NURB splines when <b>Spline/surface creation type</b> was set to <b>NURBS</b> in Configuration | S-46615 |
| Geometry  | Incorrect results when trimming closed splines with Spline Blended                                                          | R-10890 |
| Geometry  | Added display of more digits in the <b>Scale</b> field for Transform Scale to display more accurate information             | R-11133 |
| Geometry  | DZ construction plane was not being used in Transform Translate, Mirror, Scale, and Stretch                                 | R-11140 |
| Interface | Planes Manager flickered when using a 3Dconnexion SpaceMouse®                                                               | R-11071 |
| Toolpaths | Guided chaining defaulted to wrong next branch                                                                              | R-10995 |

| Category  | Name                                                                                                                 | Number  |
|-----------|----------------------------------------------------------------------------------------------------------------------|---------|
| General   | Parasolid edge curves now import with the proper edge color if one was defined                                       | D-25415 |
| General   | Printed line width was thinner than the on-screen appearance                                                         | R-10540 |
| General   | When printing, the <b>Uniform line width</b> setting was not applied                                                 | R-10672 |
| Interface | Moving an entity used to define a plane broke its associativity                                                      | D-25740 |
| Interface | Display of sharp corners on splines moved when zooming in                                                            | R-10745 |
| Interface | Rendered view mode did not persist                                                                                   | R-10854 |
| Interface | Auto highlight now shows when in a function                                                                          | S-38500 |
| Interface | Window selection start was too sensitive when selecting solid faces                                                  | S-46983 |
| Toolpaths | Too much motion was trimmed with <b>Collision check- ing</b> enabled for a Surface High Speed Area Roughing toolpath | D-24368 |
| Toolpaths | Toolpath display was turned on after posting                                                                         | R-10647 |
| Toolpaths | Choosing All as the Drive setting for Toolpath/sur-<br>face selection did not work                                   | R-10718 |

| Category  | Name                                                                                            | Number  |
|-----------|-------------------------------------------------------------------------------------------------|---------|
| Toolpaths | The start height for a 2D High Speed Area Mill toolpath varied depending on the cutter diameter | R-10941 |
| Toolpaths | The <b>Retract</b> controls for C-axis drill operations were unavailable                        | R-10963 |

| Category  | Name                                                                                                 | Number  |
|-----------|------------------------------------------------------------------------------------------------------|---------|
| API       | NET-Hook: <b>EditOperationGeometry</b> method did not work when there were no previous chains        | D-25503 |
| General   | Geometry is not being saved to DXF or DWG when using <b>Save Some</b>                                | D-25528 |
| Interface | <b>Gview follows WCS</b> did not work when creating a new plane                                      | D-25043 |
| Interface | Regenerating parent operation of a <b>Trim</b> attempted to create a new plane                       | D-25045 |
| Interface | Surface sphere and torus shaded outlines were missing                                                | D-25051 |
| Toolpaths | Pressing [ <b>Shift</b> ]+[ <b>Click</b> ] triggered a relative position point during solid chaining | R-10732 |

| Category                       | Name                                                                                         | Number  |
|--------------------------------|----------------------------------------------------------------------------------------------|---------|
| Backplot/Verify/<br>Simulation | Improved translucency when running Backplot                                                  | D-24709 |
| General                        | Pasted entities copied from a hidden level were put on the wrong level                       | R-10430 |
| Interface                      | The solid edge and surface edge colors were not set to the colors specified in Configuration | D-24888 |
| Interface                      | Single character hotkeys were triggered when renaming Viewsheets                             | R-10251 |
| Reports                        | The Mill2 setup sheet template was duplicating operations                                    | R-10178 |

#### **Tech Preview 4**

| Category | Name                                                                                  | Number  |
|----------|---------------------------------------------------------------------------------------|---------|
| General  | Blanked entities in a certain CATIA v5 file did not import into Mastercam             | D-17965 |
| General  | Text was not written in the correct location when exporting to DWG or IGES file types | D-24370 |
| General  | File save time was slow on some systems when including preview bitmap                 | D-24506 |

| Category  | Name                                                                                                                                  | Number  |
|-----------|---------------------------------------------------------------------------------------------------------------------------------------|---------|
| General   | Opening a certain ProE/Creo file as an assembly and surfaces resulted in mismatched surfaces                                          | R-06210 |
| General   | Toolpath Nesting priority was not maintained                                                                                          | R-09794 |
| General   | Importing certain IGES files created incorrect surfaces on the part                                                                   | R-09998 |
| General   | Opening SOLIDWORKS 2009 files in Mastercam 2018 caused an error                                                                       | R-10024 |
| Geometry  | Extending a certain spline (NURB) converted it to a parametric spline                                                                 | R-07942 |
| Interface | There was a 4K display issue with Stock Setup and Stock Model dialog boxes                                                            | R-10043 |
| Lathe     | A certain X9 file had the <b>Unroll</b> option of Rotary Axis<br>Control enabled in error                                             | R-08981 |
| Mill-Turn | Sync manager did not display toolpaths properly                                                                                       | R-07030 |
| Mill-Turn | Arc linearization issue with helix arc output                                                                                         | D-23046 |
| Mill-Turn | Back boring bar not rendering properly                                                                                                | R-09953 |
| Toolpaths | Waterline rest passes gouged the part                                                                                                 | R-02413 |
| Toolpaths | 2D Contour toolpath with internal corner rounding produced arcs in the corners when roughing, but did not have arcs on the final pass | R-05323 |
| Toolpaths | Surface High Speed Scallop was not regenerating with 0 stock to leave                                                                 | R-09660 |
| Toolpaths | 2D High Speed Area Mill did not cut to selected geometry                                                                              | R-10084 |

## **TECH PREVIEW 3**

| Category                       | Name                                                                                       | Number  |
|--------------------------------|--------------------------------------------------------------------------------------------|---------|
| Backplot/Verify/<br>Simulation | Added Bookmark capability to Mastercam Simulator                                           | B-44273 |
| Backplot/Verify/<br>Simulation | Updated Mastercam Simulator interface with new floating toolbar for controls               | B-44512 |
| Backplot/Verify/<br>Simulation | Wireframe arc entities displayed incorrectly in Mastercam Simulator                        | D-23506 |
| Backplot/Verify/<br>Simulation | Backplot <b>Helix Bore</b> cycle time was missing with control compensation                | D-23571 |
| Backplot/Verify/<br>Simulation | Mastercam Simulator Options dialog box was truncated on translated systems                 | D-23883 |
| Backplot/Verify/<br>Simulation | Backplot Options, <b>Show Lathe Home Position</b> setting did not persist                  | D-24194 |
| General                        | ProE file was missing faces                                                                | D-08505 |
| General                        | ProE file was missing faces when imported into Mastercam                                   | D-17266 |
| General                        | ProE/Creo file was missing faces when imported into Mastercam                              | D-24125 |
| General                        | ProE file did not import some geometry                                                     | R-08385 |
| General                        | Printing - Only the file name displayed in print preview, but full path displayed on print | R-09531 |
| General                        | ProE file did not import into Mastercam cleanly                                            | R-09618 |

| Category  | Name                                                                                                                       | Number  |
|-----------|----------------------------------------------------------------------------------------------------------------------------|---------|
| General   | File preview in <b>Recent Documents</b> showed blank image                                                                 | R-09657 |
| Interface | Made <b>Surface Curves</b> and <b>Pmesh</b> QuickMasks customize only options                                              | B-45202 |
| Mill      | Swept 2D operation was not correct                                                                                         | D-09793 |
| Mill      | 2D Contour remachining depth was wrong                                                                                     | R-02597 |
| Mill      | Stock model failed to regenerate                                                                                           | R-05004 |
| Mill      | 2D High Speed Toolpaths, <b>Dynamic Mill</b> and <b>Area Mill</b> images did not update when changing machining strategies | R-07809 |
| Mill-Turn | Stock model regeneration caused operation posted with plane 180° off                                                       | R-09101 |

## **TECH PREVIEW 2**

| Category      | Name                                                                                                            | Number  |
|---------------|-----------------------------------------------------------------------------------------------------------------|---------|
| Configuration | Renamed Solid edge select color and Solid face select color to Solid chaining edge and Solid chaining face loop | R-09116 |
| Configuration | Added a <b>Browse</b> button for the file path on the Files,<br>AutoSave/Backup page                            | R-09509 |
| General       | Could not highlight/select a point that was on a line                                                           | R-08867 |
| General       | AutoSave file was not saved when launched via [Alt+A] or from the File tab                                      | R-09490 |
| Interface     | Changing the tool number after regenerating caused a long delay                                                 | R-05944 |
| Interface     | Added all Toolpaths Manager toolbar commands to Options, Customize                                              | R-08023 |
| Interface     | Geometry icon was not updating after drag-<br>ging/dropping in Toolpaths Manager operations tree                | R-08888 |
| Interface     | Third-party C-Hook icon did not stay on the Quick<br>Access Toolbar (QAT)                                       | R-09335 |
| Interface     | On-screen Gview, Cplane, and Tplane gnomons would sometimes disappear                                           | R-09398 |
| Mill-Turn     | Pinch Turn associated operation did not respect custom WCS shift                                                | D-23871 |
| Toolpaths     | Circles now display for drill operations                                                                        | D-16371 |

| Category  | Name                                                                                    | Number  |
|-----------|-----------------------------------------------------------------------------------------|---------|
| Toolpaths | Made <b>Geometry</b> the default source mode for Toolpath Transform                     | R-04695 |
| Toolpaths | Changing the tool number after regenerating caused a long delay                         | R-05944 |
| Toolpaths | Block Drill toolpath display did not show all drill moves                               | R-08428 |
| Toolpaths | Stock Setup measured from world origin when Solid<br>Models included Boolean operations | R-09058 |

## **TECH PREVIEW 1**

| Category                       | Name                                                                                                 | Number  |
|--------------------------------|------------------------------------------------------------------------------------------------------|---------|
| API                            | Added the ability to export operations using a NET-Hook                                              | B-44330 |
| API                            | NET-Hook - Thread Mill Linking parameters failed                                                     | D-22175 |
| Backplot/Verify/<br>Simulation | Lathe tool insert projection was incorrect in Master-<br>cam Simulator                               | D-20821 |
| Backplot/Verify/<br>Simulation | Could not backplot a chamfer tool with a 0 tip diameter                                              | D-21663 |
| Configuration                  | Added an <b>Opacity</b> slider for <b>Dimmed wireframe</b> on the System Configuration, Shading page | R-09106 |
| General                        | Multi-colored solid saved to a Parasolid file had color information unreadable by other software     | R-07097 |
| General                        | Converters - Added face color support to ACIS SAT export                                             | R-07331 |
| General                        | Converters - Importing a certain DXF file defaulted the decimal place to 0                           | R-08576 |
| General                        | Improved selection performance with multiple meshes                                                  | B-43346 |
| General                        | Much improved performance in several areas, such as loading files and regenerating operations        | B-43715 |
| General                        | SOLIDWORKS assembly file could not be read                                                           | D-21441 |

| Category | Name                                                                                                                        | Number  |
|----------|-----------------------------------------------------------------------------------------------------------------------------|---------|
| General  | Importing a certain SOLIDWORKS file crashed Mastercam if Import Mastercam toolpath data from SOLIDWORKS files was turned on | D-21595 |
| General  | Nesting - <b>Priority</b> setting was not working correctly                                                                 | D-22126 |
| General  | File name was sometimes not displayed when using<br>Name/Date setting                                                       | D-23214 |
| General  | Converters - Clicking <b>Options</b> sometimes opened the wrong Options dialog when no file was selected                    | D-23680 |
| General  | Converters - Select Layout to Import dialog box did not always display when opening AutoCAD DWG/DXF files                   | R-07398 |
| General  | Reinstated <b>Open Shared Folder</b> and <b>Open User Folder</b> commands                                                   | R-07944 |
| General  | Status bar did not update after Copy was complete                                                                           | R-08114 |
| General  | Nesting - Change location of temporary files to<br>Mastercam temporary folder                                               | R-08133 |
| General  | Lathe Entry (and Wire) License gave a warning when creating a Zip2Go (.z2g) file                                            | R-08143 |
| General  | Solid face colors were sometimes printed when they should not have been                                                     | R-08477 |
| General  | <b>Snap to Grid</b> was not working properly for custom planes                                                              | R-08816 |
| Geometry | Solid Extrude automatically switched to <b>Distance</b> when the distance value was modified                                | R-07255 |
| Geometry | Flat Boundary Surface did not create a surface on all selected boundaries                                                   | D-21687 |

| Category  | Name                                                                                           | Number  |
|-----------|------------------------------------------------------------------------------------------------|---------|
| Geometry  | Imported toolpaths with geometry placed at the origin, shifted the geometry                    | R-06815 |
| Interface | Added Attributes to Home tab and mini-toolbar                                                  | R-07321 |
| Interface | Fixed issue that <b>Tab</b> key did not validate and move to the next field when MRU was open  | R-07328 |
| Interface | Resulting colors being saved were not behaving the same in X9 and 2017                         | R-08213 |
| Interface | Machine Group Properties not minimized properly when the Managers were undocked                | R-08492 |
| Interface | Improved window selection rectangle                                                            | B-39449 |
| Interface | Import button on Context Menu page now includes workspace files                                | B-39621 |
| Interface | Improved window selection polygon                                                              | B-39713 |
| Interface | Improved tessellation performance of complex surfaces                                          | B-41324 |
| Interface | Added <b>Lock all</b> and <b>Unlock all</b> options to Planes<br>Manager's right-click menu    | B-44306 |
| Interface | Levels list was not always refreshed on File, Merge                                            | D-21944 |
| Interface | Toolpaths Manager - Legacy file was regenerating with mirrored toolpath                        | D-23156 |
| Interface | Fixed corrupt workspace files in Mastercam 2017                                                | D-23189 |
| Interface | Opening a specific file caused planes used in operations to be changed                         | D-23630 |
| Interface | Customizing the Quick Access Toolbar included drop-<br>down menus but not individual functions | R-05814 |

| Category  | Name                                                                                         | Number  |
|-----------|----------------------------------------------------------------------------------------------|---------|
| Interface | Operations - Changing the tool number after regenerating caused long delay                   | R-05944 |
| Interface | Changing operation type, then closing did not mark operation dirty, but NCI was bad          | R-06947 |
| Interface | Planes Manager - Default Z direction was sometimes wrong when creating a plane from surfaces | R-07011 |
| Interface | Planes - Added support to create <b>Isometric</b> plane in Create Relative Planes            | R-07035 |
| Interface | Changed From line normal planes option to From entity normal                                 | R-07168 |
| Interface | Added file modified indicator and standardized file name in Mastercam title bar              | R-07245 |
| Interface | Copying surfaces between levels blanked some entities                                        | R-07333 |
| Interface | Imported operations also imported all locked planes                                          | R-07439 |
| Interface | Planes Manager - Added <b>Recent Function</b> support to menu items                          | R-07479 |
| Interface | Planes - Added commands for all system planes to Customize                                   | R-07967 |
| Interface | Delete no longer functioned after <b>Invert Selection</b> was toggled in AutoCursor toolbar  | R-08255 |
| Interface | Remember resizing of recent documents list in Mastercam                                      | R-08264 |
| Interface | Scrolling in the Toolpaths Manager became zooming in the graphics window in Windows 7        | R-08290 |


| Category  | Name                                                                                               | Number  |
|-----------|----------------------------------------------------------------------------------------------------|---------|
| Interface | Added Quick Mask Levels back into the interface and the command list                               | R-08327 |
| Interface | Planes Manager - <b>G</b> still showed in planes list when view was rotated with 3D mouse          | R-08335 |
| Interface | Arc MultiEdit icon was missing                                                                     | R-08336 |
| Interface | Tabs reordered themselves when modified in user workspace                                          | R-08383 |
| Interface | Can now remove a document from recent document list                                                | R-08433 |
| Interface | Expanded the <b>Name</b> column/field when the Levels Manager was resized                          | R-08542 |
| Interface | Mill Toolpath tab displayed in Design mode                                                         | R-08608 |
| Interface | Operations - Options set in Import dialog box did not persist                                      | R-08887 |
| Interface | Added math functionality to on-screen gnomon entry fields                                          | R-09061 |
| Interface | Added Refresh levels back to Levels Manager                                                        | R-09115 |
| Lathe     | Fixed Dynamic turning gouge caused by plunge cut parameters being partially ignored                | R-07299 |
| Lathe     | Improper lathe stock boundary occurred when stock boundary was broken in two pieces at end of step | R-07745 |
| Lathe     | Lathe stock warning was displayed when blanking entities                                           | R-08474 |
| Lathe     | Fixed selection of center tool                                                                     | B-41109 |

| Category | Name                                                                                                                   | Number              |
|----------|------------------------------------------------------------------------------------------------------------------------|---------------------|
| Lathe    | Lathe plunge turn toolpath retract feed rate usage was incorrect                                                       | D-21207             |
| Lathe    | Lathe rough did not respect plunge feed rate                                                                           | D-21282             |
| Lathe    | Stock Update Parameters - Cutoff stock images did not match selected settings for right spindle                        | D-21844             |
| Lathe    | Tool Inspection was not going to <b>Retract Point</b> when <b>Approach</b> was deselected until last pass              | D-21965             |
| Lathe    | Lathe stock update code, behavior, and help did not match                                                              | D-22870             |
| Lathe    | Changing lathe tool offset in one operation of X6 or older files forced a change in all operations using the same tool | R-04088             |
| Lathe    | Editing Plunge Turn operation defaults crashed<br>Mastercam                                                            | R-07923             |
| Lathe    | Lathe Reference Points handled with inconsistent priority                                                              | R-08357             |
| Lathe    | Lathe Cutoff and Plunge toolpaths crashed when<br>Show library tools was selected on Toolpath para-<br>meters tab      | R-08675             |
| Mill     | Made Thread Mill Linking parameters more like other toolpaths                                                          | B-30184             |
| Mill     | Error message appeared for disabled field                                                                              | R-07357/<br>R-08898 |
| Mill     | Toolpath Transform - Start point was being erro-<br>neously created                                                    | R-07902             |

| Category  | Name                                                                                  | Number  |
|-----------|---------------------------------------------------------------------------------------|---------|
| Mill-Turn | <b>Repair File</b> created multiple copies of Code Expert in Mill-Turn                | R-08614 |
| Mill-Turn | Added ability to chain geometry on multiple planes, (similar to lathe chaining)       | B-42381 |
| Mill-Turn | Sequence numbers did not output when token UseNCSpaces was set to <b>False</b>        | D-21868 |
| Mill-Turn | Tap feed rate was posted as zero                                                      | D-22361 |
| Mill-Turn | Stock model was incorrect when using pinch turn operation                             | D-22650 |
| Mill-Turn | Mill-Turn stock pull did not put new geometry on the proper level                     | D-22880 |
| Mill-Turn | WCS check invoked for operations on import                                            | R-06446 |
| Mill-Turn | 2D Contour Use entry point was not working unless<br>Mill type was re-selected        | R-07444 |
| Mill-Turn | Tool number could not be bigger than maximum station number for turret park operation | R-08718 |
| Mill-Turn | IOF file failed to generate when invalid characters were used                         | R-08925 |
| Mill-Turn | Custom WCS caused mill tools to not load                                              | R-09172 |
| Tooling   | Selecting a tool from the tool library did not use that tool in the toolpath          | R-07372 |
| Tooling   | Fixed crash that occurred when using Tool Wizard                                      | B-43386 |
| Tooling   | Custom tool not rendered via TSM or Local machine definition                          | D-22163 |

| Category  | Name                                                                                 | Number  |
|-----------|--------------------------------------------------------------------------------------|---------|
| Tooling   | The message, "Tessellating" displayed after exiting the Tool Definition dialog box   | R-07251 |
| Tooling   | Tap feeds and speeds were sometimes out of sync                                      | R-07369 |
| Tooling   | Fixed assert occurring in Active Reports with a custom tool                          | R-07411 |
| Toolpaths | Reports - HST Surface operations output had incorrect stepover and stepdown values   | R-07358 |
| Toolpaths | Disabled Chaining Wireframe mode if only solids were visible                         | B-41504 |
| Toolpaths | Keep Tool Down value gouged part                                                     | D-08491 |
| Toolpaths | Incorrect chaining tolerance was displayed in some toolpath Chaining dialog boxes    | D-21335 |
| Toolpaths | Reports - Plunge Turn stock to leave values were not output in reports               | D-21519 |
| Toolpaths | Reports - Incorrect plunge rate (from tool definition) was output in reports         | D-21524 |
| Toolpaths | Toolpath nesting of clusters crashed Mastercam                                       | D-21616 |
| Toolpaths | Setup sheet incorrectly called custom tool parameters                                | D-21757 |
| Toolpaths | Large icon setting was not retained                                                  | D-22578 |
| Toolpaths | Code Editor string did not match ID description                                      | D-22581 |
| Toolpaths | Reports - Added simplified Mill2-style setup sheet report                            | R-04968 |
| Toolpaths | Stock Model took a very long time to process with reasonably-sized source operations | R-05471 |

| Category  | Name                                                                                                        | Number  |
|-----------|-------------------------------------------------------------------------------------------------------------|---------|
| Toolpaths | Toolpath Transform - NCI rotating Surface Finish Flowline was sometimes producing incorrect arcs            | R-05885 |
| Toolpaths | 360 degree arc from arc/filter caused gouge in 3D HST                                                       | R-06559 |
| Toolpaths | Setup Sheet report with Wire SZ data was output under SZ-M instead of SZ-W                                  | R-06849 |
| Toolpaths | 2D contour operation was marked clean after rechaining all, but then canceling out of Parameters dialog box | R-07141 |
| Toolpaths | Reports - Detailed report showed incorrect holder when run from lower window                                | R-07381 |
| Toolpaths | ATP - Added option to leave the last processed part open                                                    | R-07924 |
| Toolpaths | Improved cancellation of toolpath creation process                                                          | R-08015 |
| Toolpaths | Chaining Color Mask dialog did not re-size, truncating the display                                          | R-08502 |
| Wire      | Taper angle changed with regeneration and comment moved <b>Taper ON</b> code                                | R-07489 |
| Wire      | Offset changed in Wire Contour operation when copied and regenerated                                        | D-22191 |



CNC Software, Inc. 671 Old Post Road Tolland, CT 06084 USA www.mastercam.com















